

Message Text

CONFIDENTIAL

PAGE 01 WELLIN 01115 082227Z
ACTION SY-05

INFO OCT-01 EA-10 NEA-10 ISO-00 OC-06 CCO-00 OCL-00
FBOE-00 A-01 /033 W

-----023028 082233Z /15

O R 060440Z MAR 78 ZDK CITE MVC 124
FM AMEMBASSY WELLINGTON
TO AMEMBASSY CANBERRA IMMEDIATE
INFO SECSTATE WASHDC 5084
AMEMBASSY BANGKOK
AMEMBASSY DACCA
AMCONSUL HONG KONG
AMEMBASSY MANILA

C O N F I D E N T I A L WELLINGTON 01115

DEPT. FOR SY/OPS/T; DACCA FOR OIC/RTC; CANBERRA FOR
HIMMELBERGER; BANGKOK FOR BEAUDOIN; MANILA FOR ATO AND
TSO BRANDT; HONG KONG FOR RTC/RSS

EO 11652: GDS
TAGS: ASEC, AFAC, ABLD
SUBJECT: CCC INSTALLATION AND REPAIR WORK

REF: PORT MORESBY 0316

REFTEL PARA 3A, POST HAS NOT RECEIVED UNIT, WILL
TELEGRAPH WASHINGTON FOR ETA. HOWEVER, THE TWO WATER
PUMPS INSTALLED (3/1) APPEAR TO HAVE RESOLVED THE
PROBLEM IN THE CCC AREA. PRESENT TEMPERATURE READING
IS A STEADY 70 DEGREES. THE REPLACEMENT UNIT TSF-081C
INSTALLATION MAY NOT BE NECESSARY.

3B - ALL ELECTRICAL PARTS WILL BE FURNISHED. THE ONLY
REQUIRED WORK NECESSARY IS CONNECTING PREWIRE TO THE
THERMOSTAT. JOB TIME, TWO DAYS MAX.

CONFIDENTIAL

CONFIDENTIAL

PAGE 02 WELLIN 01115 082227Z

3D - FAN COIL UNIT FOR ACR ROOM (228) WILL BE INSTALLED
BY CONTRACTOR.

3E/F - POST WILL PROCURE MATERIALS REQUESTED. SELDEN

NOTE BY OC/T: TELEGRAM DELAYED IN TRANSMISSION.

CONFIDENTIAL

NNN

Message Attributes

Automatic Decaptioning: Z
Capture Date: 01 jan 1994
Channel Indicators: n/a
Current Classification: UNCLASSIFIED
Concepts: n/a
Control Number: n/a
Copy: SINGLE
Draft Date: 06 mar 1978
Decaption Date: 20 Mar 2014
Decaption Note: 25 YEAR REVIEW
Disposition Action: RELEASED
Disposition Approved on Date:
Disposition Case Number: n/a
Disposition Comment: 25 YEAR REVIEW
Disposition Date: 20 Mar 2014
Disposition Event:
Disposition History: n/a
Disposition Reason:
Disposition Remarks:
Document Number: 1978WELLIN01115
Document Source: CORE
Document Unique ID: 00
Drafter: n/a
Enclosure: n/a
Executive Order: GS
Errors: N/A
Expiration:
Film Number: D780105-0117
Format: TEL
From: WELLINGTON
Handling Restrictions:
Image Path:
ISecure: 1
Legacy Key: link1978/newtext/t197803100/aaaadhhl.tel
Line Count: 61
Litigation Code IDs:
Litigation Codes:
Litigation History:
Locator: TEXT ON-LINE, ON MICROFILM
Message ID: e40681b7-c288-dd11-92da-001cc4696bcc
Office: ACTION SY
Original Classification: CONFIDENTIAL
Original Handling Restrictions: ONLY
Original Previous Classification: n/a
Original Previous Handling Restrictions: n/a
Page Count: 2
Previous Channel Indicators: n/a
Previous Classification: CONFIDENTIAL
Previous Handling Restrictions: ONLY
Reference: 78 PORT MORESBY 316
Retention: 0
Review Action: RELEASED, APPROVED
Review Content Flags:
Review Date: 02 may 2005
Review Event:
Review Exemptions: n/a
Review Media Identifier:
Review Release Date: n/a
Review Release Event: n/a
Review Transfer Date:
Review Withdrawn Fields: n/a
SAS ID: 3101473
Secure: OPEN
Status: NATIVE
Subject: CCC INSTALLATION AND REPAIR WORK
TAGS: ASEC, AFAC, ABLD
To: CANBERRA
Type: TE
vdkgvwkey: odbc://SAS/SAS.dbo.SAS_Docs/e40681b7-c288-dd11-92da-001cc4696bcc
Review Markings:
Sheryl P. Walter
Declassified/Released
US Department of State
EO Systematic Review
20 Mar 2014
Markings: Sheryl P. Walter Declassified/Released US Department of State EO Systematic Review 20 Mar 2014